



SPECTRUM[®]

MODULAR VISCOUS FAN DRIVES
by Kit Masters

Cross-Reference Guide

99%

**of all Viscous Fan Drives
IN STOCK NOW!**

Available at your Spectrum® distributor



SPECTRUM®
MODULAR VISCOUS FAN DRIVES
by Kit Masters

HOW IS THIS POSSIBLE?

By creating several universal viscous heads, along with interchangeable brackets and adapters, Kit Masters has narrowed the field of viscous fan drives from over 1,000 part numbers, down to just a few components. This unprecedented system makes it possible to have access to a replacement for nearly every viscous fan drive.


1000'S OF INDIVIDUAL PART NUMBERS



THE OLD WAY

- 1,000's of part numbers
- No 80/20 rule
- Huge investment required to have all of the parts in stock
- Long lead times
- Many parts are obsolete

19 INTERCHANGEABLE BRACKETS



PLUS 7 HEADS



EQUALS THOUSANDS OF PARTS!

THE SPECTRUM WAY

- Modular program requires dramatically less inventory
 - 7 heads
 - 19 brackets
 - 11 adapters
- 99% market coverage
- Eliminates lead time
- Reduce lost sales on obsolete parts
- OEM Approved
- Competitively priced

USING THIS CROSS-REFERENCE GUIDE

Your original
part #

New part number for
Spectrum clutch

Components for building your new clutch

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
18049-1	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
18088-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18088-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18092-1	RV0222300-00	RV-H02	RV-223	-	-	-

STEP 1

Locate your viscous clutch part number* in the left hand column. In the example below, part number 18088-1.

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
18049-1	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
18088-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18088-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-

STEP 2

Locate and gather required components.

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
18049-1	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
18088-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18088-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-

STEP 3



Assemble clutch according to instructions on page 6.

*If you do not have a part number, refer to page 5 for tips on identifying your fan clutch.

IDENTIFY YOUR VISCOUS CLUTCH

Check for part numbers.

Part numbers are usually located on the center of the clutch by the coil (A), or along the outside edge of the clutch (B). If you have a part number, refer to the Spectrum cross-reference guide or go to www.kitmasters.com to find your new part number.



If no part numbers are available then gather the following information:

1. What is your fan size? Measure in inches.

2. What is the rotation of the fan clutch (CW or CCW)? Look at your truck from the front to determine this.

3. What is the mount type?

Bolt-on or Screw-on

If Bolt-on, answer questions 4 through 8.


If Screw-on, answer questions 6 through 9.



Bolt-on mount style



Screw-on mount style



4. What is the Drive Bolt Circle measurement?

5. What is the Drive Pilot measurement?

6. What is the Length measurement?

7. What is the Fan Pilot measurement?

8. What is the Fan Bolt Circle measurement?

9. What is the Thread Type?


Use thread gauges, included with Spectrum cart (red bin).

- a) .75-16UNF-2B LH
- b) 1.25-16UN-2B LH
- c) 1.25-18UNEF-2B RH
- d) 2.25-8UNC-2A LH
- e) M30x2-6H LH
- f) M36x2-6H LH

Once you have all of this information, go to www.kitmasters.com/spectrum and enter these measurements to determine the required replacement.

ASSEMBLING YOUR NEW MODULAR VISCOUS FAN DRIVE

1. Insert viscous head (a) into the holding cradle on the top of the Spectrum cart.
2. Add any required special adapters (not on all clutches)
 - a. Follow instructions included with special adapters
3. Start threading (by hand) the bracket (b) into the receiving nut (c).
 - All brackets thread into the head counterclockwise except when using head number RV-HO3.
4. Refer to chart below to determine required wrench type.
 - 2" Socket & spanner wrench are included with Spectrum cart.
5. Use appropriate wrench to torque bracket to head.
 - Refer to chart below for torque specs.
6. If pilot adapter is required, do not install until you are ready to mount clutch on vehicle.



BRACKET #	WRENCH TYPE	TORQUE SPECS (FT. LBS.)
RV-101	2" Socket	80
RV-102	2" Socket	80
RV-103	2" Socket	80
RV-104	2" Socket	80
RV-105	2" Socket	80
RV-106	2" Socket	60
RV-107	2" Socket	60
RV-108	2" Socket	60
RV-109	2" Socket	60
RV-110	2" Socket	60
RV-111	2" Socket	60
RV-201	Spanner	80
RV-202	Spanner	80
RV-203	Spanner	60
RV-204	3/8" Square Drive	80
RV-205	3/8" Square Drive	80
RV-206	3/8" Square Drive	80
RV-207	3/8" Square Drive	80
RV-208	Spanner	80

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
010010980	RV0511200-00	RV-H05	RV-112	-	-	-
010010981	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
010010992	RV0420400-00	RV-H04	RV-204	-	-	-
010010993	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
010011210	RV0411300-00	RV-H04	RV-113	-	-	-
010011657	RV0421800-00	RV-H04	RV-218	-	-	-
010011790	RV0420400-00	RV-H04	RV-204	-	-	-
010018941	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
010019000	RV0211700-00	RV-H02	RV-117	-	-	-
010019556	RV0610400-03	RV-H06	RV-104	-	RV-S03	-
010019561	RV0210800-03	RV-H02	RV-108	-	RV-S03	-
010019721	RV0410100-00	RV-H04	RV-101	-	-	-
010020069	RV0522005-00	RV-H05	RV-220	RV-P05	-	-
010020164	RV0611200-02	RV-H06	RV-112	-	RV-S02	-
010020509	RV0311100-00	RV-H03*	RV-111	-	-	-
010020552	RV0311100-00	RV-H03*	RV-111	-	-	-
010020755	RV0210900-00	RV-H02	RV-109	-	-	-
010020791	RV0311100-00	RV-H03*	RV-111	-	-	-
010020805	RV0410500-00	RV-H04	RV-105	-	-	-
010020893	RV0210900-00	RV-H02	RV-109	-	-	-
010020914	RV0210900-00	RV-H02	RV-109	-	-	-
010021288	RV0710400-03	RV-H07	RV-104	-	RV-S03	-
010021314	RV0410200-00	RV-H04	RV-102	-	-	-
010021454	RV0710500-00	RV-H07	RV-105	-	-	-
010021483	RV0210700-00	RV-H02	RV-107	-	-	-
010021488	RV0410300-00	RV-H04	RV-103	-	-	-
010021511	RV0210600-00	RV-H02	RV-106	-	-	-
010021524	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
010021525	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
010021526	RV0610400-03	RV-H06	RV-104	-	RV-S03	-
010021530	RV0610500-00	RV-H06	RV-105	-	-	-
010021531	RV0510500-00	RV-H05	RV-105	-	-	-
010021532	RV0410500-00	RV-H04	RV-105	-	-	-
010021584	RV0420400-00	RV-H04	RV-204	-	-	-
010021585	RV0522006-00	RV-H05	RV-220	RV-P06	-	-
010021586	RV0421309-00	RV-H04	RV-213	RV-P09	-	-
010021587	RV0421800-00	RV-H04	RV-218	-	-	-
010021726	RV0710500-01	RV-H07	RV-105	-	RV-S01	-
010021792	RV0410100-00	RV-H04	RV-101	-	-	-
010022047	RV0420400-00	RV-H04	RV-204	-	-	-
010022048	RV0520400-00	RV-H05	RV-204	-	-	-
010022049	RV0420600-00	RV-H04	RV-206	-	-	-
010022050	RV0521900-00	RV-H05	RV-219	-	-	-
010022367	RV0410100-00	RV-H04	RV-101	-	-	-
010022541	RV0421900-00	RV-H04	RV-219	-	-	-
010023060	RV0122200-00	RV-H01	RV-222	-	-	-
010023312	RV0120301-03	RV-H01	RV-203	RV-P01	RV-S03	-
010023319	RV0420201-00	RV-H04	RV-202	RV-P01	RV-S03	-
010023323	RV0220301-03	RV-H02	RV-203	RV-P01	RV-S03	-
010023346	RV0121500-00	RV-H01	RV-215	-	-	-
010023364	RV0311100-00	RV-H03*	RV-111	-	-	-
010023365	RV0520201-00	RV-H05	RV-202	RV-P01	-	-
010023474	RV0620101-00	RV-H06	RV-201	RV-P01	-	-
010023513	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
010023608	RV0520500-00	RV-H05	RV-205	-	-	-

* Thread bracket clockwise into RV-H03

BORGWARNER

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
010023757	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
010023768	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
010023963	RV0710400-03	RV-H07	RV-104	-	RV-S03	-
010023971	RV0421800-00	RV-H04	RV-218	-	-	-
010024281	RV0410300-00	RV-H04	RV-103	-	-	-
1210-09155-01	RV0210900-00	RV-H02	RV-109	-	-	-
1210-09156-02	RV0311100-00	RV-H03*	RV-111	-	-	-
1210-09157-01	RV0410500-00	RV-H04	RV-105	-	-	-
1210-09157-02	RV0311100-00	RV-H03*	RV-111	-	-	-
1210-09157-03	RV0210900-00	RV-H02	RV-109	-	-	-
1210-09157-05	RV0311100-00	RV-H03*	RV-111	-	-	-
1210-09167-02	RV0210700-00	RV-H02	RV-107	-	-	-
1210-09167-03	RV0210900-00	RV-H02	RV-109	-	-	-
1210-09167-04	RV0820700-00	RV-H08	RV-207	-	-	-
1210-09167-51	RV0820800-00	RV-H08	RV-208	-	RV-S03	-
1210-09167-54	RV0210600-00	RV-H02	RV-106	-	-	-
1210-09168-03	RV0610500-00	RV-H06	RV-105	-	-	-
1210-09168-05	RV0410500-00	RV-H04	RV-105	-	-	-
1210-09168-10	RV0420400-00	RV-H04	RV-204	-	-	-

EATON

16233-2	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
16557-1	RV0220303-00	RV-H02	RV-203	RV-P03	-	-
16650-2	RV0720110-00	RV-H07	RV-201	RV-P10	-	-
17284-1	RV0420101-00	RV-H04	RV-201	RV-P01	-	-
17310-1	RV0322615-00	RV-H03*	RV-226	RV-P15	-	-
17398-1	RV0120308-00	RV-H01	RV-203	RV-P08	-	-
17449-1	RV0220813-00	RV-H02	RV-208	RV-P13	RV-S03	New Fan Required
17456-1	RV0420100-00	RV-H04	RV-201	-	-	-
17487-3	RV0122402-02	RV-H01	RV-224	RV-P02	RV-S02	New Fan Required
17497-1	RV0221507-00	RV-H02	RV-215	RV-P07	-	-
17545-1	RV0220300-00	RV-H02	RV-203	-	-	-
17562-1	RV0222300-00	RV-H02	RV-223	-	-	New Fan Required
17585-1	RV0521000-00	RV-H05	RV-210	-	-	-
17637-2	RV0611600-02	RV-H06	RV-116	-	RV-S02	-
17671-1	RV0120300-00	RV-H01	RV-203	-	-	-
17708-2	RV0420100-00	RV-H04	RV-201	-	-	-
17713-1	RV0520200-00	RV-H05	RV-202	-	RV-S03	-
17740-3	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
17740-4	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
17858-1	RV0322609-03	RV-H03*	RV-226	RV-P09	RV-S03	-
17866-1	RV0522005-00	RV-H05	RV-220	RV-P05	-	-
17881-1	RV0122300-00	RV-H01	RV-223	-	-	-
17882-1	RV0122300-00	RV-H01	RV-223	-	-	New Fan Required
17891-1	RV0222300-00	RV-H02	RV-223	-	-	-
17898-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
17906-1	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
17908-2	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
17913-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
17913-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
17915-1	RV0722100-00	RV-H07	RV-221	-	-	-
17926-3	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
17939-1	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
17969-1	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
18019-1	RV0122312-00	RV-H01	RV-223	RV-P12	-	-

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
18049-1	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
18088-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18088-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18092-1	RV0222300-00	RV-H02	RV-223	-	-	-
18100-1	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
18105-1	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
18115-1	RV0220300-00	RV-H02	RV-203	-	-	-
18164-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18168-1	RV0521000-00	RV-H05	RV-210	-	-	-
18192-1	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
18197-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18225-1	RV0522005-00	RV-H05	RV-220	RV-P05	-	-
18284-1	RV0711200-02	RV-H07	RV-112	-	RV-S02	-
18284-2	RV0711200-02	RV-H07	RV-112	-	RV-S02	-
18296-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18299-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18324-1	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
18327-2	RV0720201-00	RV-H07	RV-202	RV-P01	-	-
18359-1	RV0222300-00	RV-H02	RV-223	-	-	-
18421-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18424-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18424-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18425-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18426-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18426-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18467-1	RV0420101-00	RV-H04	RV-201	RV-P01	-	-
18521-1	RV0110600-00	RV-H01	RV-106	-	-	-
18522-1	RV0110600-00	RV-H01	RV-106	-	-	-
18523-1	RV0420900-00	RV-H04	RV-209	-	-	-
18627-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18627-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18645-1	RV0121709-00	RV-H01	RV-217	RV-P09	-	-
18672-1	RV0420100-00	RV-H04	RV-201	-	-	-
18676-1	RV0420200-00	RV-H04	RV-202	-	-	-
18682-2	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
18783-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18784-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18786-1	RV0411400-00	RV-H04	RV-114	-	-	-
18801-1	RV0222500-00	RV-H02	RV-225	-	-	-
18806-1	RV0221700-00	RV-H02	RV-217	-	-	-
18838-2	RV0110600-00	RV-H01	RV-106	-	-	-
18890-1	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
18891-2	RV0721100-01	RV-H07	RV-211	-	RV-S01	-
18898-1	RV0721000-01	RV-H07	RV-210	-	RV-S01	-
18937-1	RV0711200-02	RV-H07	RV-112	-	RV-S02	-
18963-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
18968-1	RV0711300-00	RV-H07	RV-113	-	-	-
19025-1	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
19026-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
19044-1	RV0720900-01	RV-H07	RV-209	-	RV-S01	-
19137-1	RV0711300-01	RV-H07	RV-113	-	RV-S01	-
19170-1	RV0620200-00	RV-H06	RV-202	-	RV-S03	-
19179-1	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
19180-1	RV0421309-00	RV-H04	RV-213	RV-P09	-	-
EV-16233-2	RV0720101-00	RV-H07	RV-201	RV-P01	-	-

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
EV-16557-1	RV0220303-00	RV-H02	RV-203	RV-P03		-
EV-16650-2	RV0720110-00	RV-H07	RV-201	RV-P10	-	-
EV-17284-1	RV0420101-00	RV-H04	RV-201	RV-P01	-	-
EV-17310-1	RV0322615-00	RV-H03*	RV-226	RV-P15	-	-
EV-17398-1	RV0120308-00	RV-H01	RV-203	RV-P08		-
EV-17449-1	RV0220813-00	RV-H02	RV-208	RV-P13	RV-S03	New Fan Required
EV-17456-1	RV0420100-00	RV-H04	RV-201	-	-	-
EV-17487-3	RV0122402-02	RV-H01	RV-224	RV-P02	RV-S02	New Fan Required
EV-17497-1	RV0221507-00	RV-H02	RV-215	RV-P07	-	-
EV-17545-1	RV0220300-00	RV-H02	RV-203	-	-	-
EV-17562-1	RV0222300-00	RV-H02	RV-223	-	-	New Fan Required
EV-17585-1	RV0521000-00	RV-H05	RV-210	-	-	-
EV-17637-2	RV0611600-02	RV-H06	RV-116	-	RV-S02	-
EV-17671-1	RV0120300-00	RV-H01	RV-203	-	-	-
EV-17708-2	RV0420100-00	RV-H04	RV-201	-	-	-
EV-17713-1	RV0520200-00	RV-H05	RV-202	-	RV-S03	-
EV-17740-3	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
EV-17740-4	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
EV-17858-1	RV0322609-03	RV-H03*	RV-226	RV-P09	RV-S03	-
EV-17866-1	RV0522005-00	RV-H05	RV-220	RV-P05	-	-
EV-17881-1	RV0122300-00	RV-H01	RV-223	-	-	-
EV-17882-1	RV0122300-00	RV-H01	RV-223	-	-	New Fan Required
EV-17891-1	RV0222300-00	RV-H02	RV-223	-		-
EV-17898-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-17906-1	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
EV-17908-2	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
EV-17913-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-17913-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-17915-1	RV0722100-00	RV-H07	RV-221	-	-	-
EV-17926-3	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
EV-17939-1	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
EV-17969-1	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
EV-18019-1	RV0122312-00	RV-H01	RV-223	RV-P12	-	-
EV-18049-1	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
EV-18088-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18088-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18092-1	RV0222300-00	RV-H02	RV-223	-	-	-
EV-18100-1	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
EV-18105-1	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
EV-18115-1	RV0220300-00	RV-H02	RV-203	-	-	-
EV-18164-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18168-1	RV0521000-00	RV-H05	RV-210	-	-	-
EV-18192-1	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
EV-18197-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18225-1	RV0522005-00	RV-H05	RV-220	RV-P05	-	-
EV-18284-1	RV0711200-02	RV-H07	RV-112	-	RV-S02	-
EV-18284-2	RV0711200-02	RV-H07	RV-112	-	RV-S02	-
EV-18296-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18299-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18324-1	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
EV-18327-2	RV0720201-00	RV-H07	RV-202	RV-P01	-	-
EV-18359-1	RV0222300-00	RV-H02	RV-223	-	-	-
EV-18421-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18424-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18424-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
EV-18425-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18426-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18426-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18467-1	RV0420101-00	RV-H04	RV-201	RV-P01	-	-
EV-18521-1	RV0110600-00	RV-H01	RV-106	-	-	-
EV-18522-1	RV0110600-00	RV-H01	RV-106	-	-	-
EV-18523-1	RV0420900-00	RV-H04	RV-209	-	-	-
EV-18627-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18627-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18645-1	RV0121709-00	RV-H01	RV-217	RV-P09	-	-
EV-18672-1	RV0420100-00	RV-H04	RV-201	-	-	-
EV-18676-1	RV0420200-00	RV-H04	RV-202	-	-	-
EV-18682-2	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
EV-18783-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18784-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18786-1	RV0411400-00	RV-H04	RV-114	-	-	-
EV-18801-1	RV0222500-00	RV-H02	RV-225	-	-	-
EV-18806-1	RV0221700-00	RV-H02	RV-217	-	-	-
EV-18838-2	RV0110600-00	RV-H01	RV-106	-	-	-
EV-18890-1	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
EV-18891-2	RV0721100-01	RV-H07	RV-211	-	RV-S01	-
EV-18898-1	RV0721000-01	RV-H07	RV-210	-	RV-S01	-
EV-18937-1	RV0711200-02	RV-H07	RV-112	-	RV-S02	-
EV-18963-1	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-18968-1	RV0711300-00	RV-H07	RV-113	-	-	-
EV-19025-1	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
EV-19026-2	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
EV-19044-1	RV0720900-01	RV-H07	RV-209	-	RV-S01	-
EV-19137-1	RV0711300-01	RV-H07	RV-113	-	RV-S01	-
EV-19170-1	RV0620200-00	RV-H06	RV-202	-	RV-S03	-
EV-19179-1	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
EV-19180-1	RV0421309-00	RV-H04	RV-213	RV-P09	-	-

FORD

1C4Z-8A616-BA	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
1C4Z-8A616-BA	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
D7HT-8A616-AEC	RV0221600-00	RV-H02	RV-216	-	-	-
D7HZ-8A616-D	RV0221600-00	RV-H02	RV-216	-	-	-
D7HZ-8A616-G	RV0221600-00	RV-H02	RV-216	-	-	-
D7HZ-8A616-P	RV0221600-00	RV-H02	RV-216	-	-	-
D8HS-8A616-CA	RV0720111-01	RV-H07	RV-201	RV-P11	RV-S01	-
D9HT-8A616-BD	RV0221700-00	RV-H02	RV-217	-	-	-
D9HZ-8A616-C	RV0221700-00	RV-H02	RV-217	-	-	-
D9HZ-8A616-H	RV0221700-00	RV-H02	RV-217	-	-	-
E1HT-8A616-AA	RV0221714-00	RV-H02	RV-217	RV-P14	-	-
E1HZ-8A616-A	RV0221714-00	RV-H02	RV-217	RV-P14	-	-
E1HZ-8A616-G	RV0221714-00	RV-H02	RV-217	RV-P14	-	-
E2HS-8A616-AA	RV0520100-01	RV-H05	RV-201	-	RV-S01	-
E2HS-8A616-BA	RV0520100-01	RV-H05	RV-201	-	RV-S01	-
E2HT-8A616-CA	RV0221700-00	RV-H02	RV-217	-	-	-
E3HT-8A616-EC	RV0120308-00	RV-H01	RV-203	RV-P08	-	-
E3HZ-8A616-A	RV0120308-00	RV-H01	RV-203	RV-P08	-	-
E3HZ-8A616-G	RV0120308-00	RV-H01	RV-203	RV-P08	-	-
E3TZ-8A616-E	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
E4HS-8A616-CA	RV0120308-00	RV-H01	RV-203	RV-P08	-	-

FORD

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
E5HS-8A616-BA	RV0520100-01	RV-H05	RV-201	-	RV-S01	-
E5HS-8A616-DA	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
E5HS-8A627-DA	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
E5HZ-8A616-A	RV0212200-00	RV-H02	RV-122	-	-	-
E5HZ-8A616-B	RV0212200-00	RV-H02	RV-122	-	-	-
E5TA-8A616-SA	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
E5TZ-8A616-C	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
E6HS-8A616-AA	RV0520100-01	RV-H05	RV-201	-	RV-S01	-
E6HT-8A616-GA	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
E6HZ-8A616-D	RV0412100-00	RV-H04	RV-121	-	-	-
E6TA-8A616-GA	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
E6TZ-8A616-A	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
E7HT-8A616-MA	RV0221714-00	RV-H02	RV-217	RV-P14	-	-
E7HT-8A616-RA	RV0120308-00	RV-H01	RV-203	RV-P08	-	-
E7HT-8A616-SA	RV0212200-00	RV-H02	RV-122	-	-	-
E8HT-8A616-IA	RV0521200-00	RV-H05	RV-212	-	-	-
E8HT-8A616-LA	RV0521200-00	RV-H05	RV-212	-	-	-
E8HT-8A616-NA	RV0521000-00	RV-H05	RV-210	-	-	-
E8HT-8A616-SA	RV0412100-00	RV-H04	RV-121	-	-	-
E8HT-8A616-TA	RV0521200-00	RV-H05	RV-212	-	-	-
E8HZ-8A616-A	RV0720201-00	RV-H07	RV-202	RV-P01	-	-
E8HZ-8A616-J	RV0122402-02	RV-H01	RV-224	RV-P02	RV-S02	New Fan Required
E8HZ-8A616-K	RV0521200-00	RV-H05	RV-212	-	-	-
E8HZ-8A616-L	RV0412100-00	RV-H04	RV-121	-	-	-
E8HZ-8A616-M	RV0521200-00	RV-H05	RV-212	-	-	-
E8TA-8A616-PA	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
E9HZ-8A616-A	RV0521000-00	RV-H05	RV-210	-	-	-
E9HZ-8A616-B	RV0520116-01	RV-H05	RV-201	RV-P16	RV-S01	-
E9TA-8A616-EA	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
E9TZ-8A616-A	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
E9TZ-8A616-G	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
FOHS-8A616-BA	RV0520116-01	RV-H05	RV-201	RV-P16	RV-S01	-
FOHS-8A616-CA3	RV0520900-01	RV-H05	RV-209	-	RV-S01	-
FOHS-8A616-DA	RV0520900-01	RV-H05	RV-209	-	RV-S01	-
FOHT-8A616-F	RV0221507-00	RV-H02	RV-215	RV-P07	-	-
F1HT-8A616-DA	RV0611600-02	RV-H06	RV-116	-	RV-S02	-
F1HT-8A616-EA	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
F3HT-8A616-BA	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
F3HZ-8A616-B	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
F3TA-8A616-GA	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
F5TA-8A616-KB	RV0311000-02	RV-H03*	RV-110	-	RV-S02	-
F5TZ-8A616-KB	RV0311000-02	RV-H03*	RV-110	-	RV-S02	-
F7HS-8A616-AA	RV0420900-00	RV-H04	RV-209	-	-	-
F7HT-8A616-BA	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
F7HT-8A616-DA	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
F8HT-8A616-FA	RV0412100-00	RV-H04	RV-121	-	-	-
F8HT-8A616-LA	RV0521200-00	RV-H05	RV-212	-	-	-
IC44-8A616-BA	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
IC44-8A616-CB	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
XC45-8A616-AA	RV0121709-00	RV-H01	RV-217	RV-P09	-	-

FREIGHTLINER

05-12225-000	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
680-200-01-26	RV0122300-00	RV-H01	RV-223	-	-	-
680-200-02-26	RV0122300-00	RV-H01	RV-223	-	-	New Fan Required

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
15679381	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
15718025	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
15990495	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
15990496	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
15995659	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
15044771	RV0411400-00	RV-H04	RV-114	-	-	-
15504174	RV0220303-00	RV-H02	RV-203	RV-P03	-	-
15684550	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
15716073	RV0411200-02	RV-H04	RV-112	-	RV-S02	-

HORTON

9802000	RV0222300-00	RV-H02	RV-223	-		-
9802001	RV0122300-00	RV-H01	RV-223	-	-	-
9802002	RV0220300-00	RV-H02	RV-203	-	-	-
9802003	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
9802004	RV0410500-00	RV-H04	RV-105	-	-	-
9802005	RV0410500-00	RV-H04	RV-105	-	-	-
9802008	RV0311100-00	RV-H03*	RV-111	-	-	-
9802009	RV0421309-00	RV-H04	RV-213	RV-P09	-	-
9802012	RV0410500-00	RV-H04	RV-105	-	-	-
9802013	RV0410500-00	RV-H04	RV-105	-	-	-
9802015	RV0610500-00	RV-H06	RV-105	-	-	-
9803000	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
9803002	RV0410500-00	RV-H04	RV-105	-	-	-
9902000	RV0222300-00	RV-H02	RV-223	-		-
9902001	RV0122300-00	RV-H01	RV-223	-	-	-
9902002	RV0220300-00	RV-H02	RV-203	-	-	-
9902003	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
9902004	RV0410500-00	RV-H04	RV-105	-	-	-
9902005	RV0410500-00	RV-H04	RV-105	-	-	-
9902007	RV0311100-00	RV-H03*	RV-111	-	-	-
9902008	RV0311100-00	RV-H03*	RV-111	-	-	-
9902009	RV0421309-00	RV-H04	RV-213	RV-P09	-	-
9902012	RV0410500-00	RV-H04	RV-105	-	-	-
9902013	RV0410500-00	RV-H04	RV-105	-	-	-
9902015	RV0610500-00	RV-H06	RV-105	-	-	-
9903000	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
9903001	RV0410500-00	RV-H04	RV-105	-	-	-
9903002	RV0410500-00	RV-H04	RV-105	-	-	-

INTERNATIONAL

0488330C1	RV0520203-00	RV-H05	RV-202	RV-P03	-	-
0489271C1	RV0222402-03	RV-H02	RV-224	RV-P02	RV-S03	New Fan Required
0494344C1	RV0120702-00	RV-H01	RV-207	RV-P02	-	New Fan Required
0503192C91	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
0504909C1	RV0220301-00	RV-H02	RV-203	RV-P01		-
0504910C1	RV0220301-00	RV-H02	RV-203	RV-P01		-
0507271C2	RV0520101-01	RV-H05	RV-201	RV-P01	RV-S01	-
0534319C1	RV0720201-00	RV-H07	RV-202	RV-P01	-	-
0537481C1	RV0220301-00	RV-H02	RV-203	RV-P01		-
0557146C91	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
0587655C1	RV0220301-00	RV-H02	RV-203	RV-P01		-
0587656C1	RV0220301-00	RV-H02	RV-203	RV-P01		-
0996121C92	RV0220813-00	RV-H02	RV-208	RV-P13	RV-S03	New Fan Required
0996121C93	RV0220813-00	RV-H02	RV-208	RV-P13	RV-S03	New Fan Required

* Thread bracket clockwise into RV-H03

INTERNATIONAL

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
0999643C91	RV0220813-00	RV-H02	RV-208	RV-P13	RV-S03	New Fan Required
1606005C92	RV0221500-00	RV-H02	RV-215	-	-	-
1607003C91	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
1609989C91	RV0220301-00	RV-H02	RV-203	RV-P01	-	-
1612269C1	RV0520101-01	RV-H05	RV-201	RV-P01	RV-S01	-
1612269C2	RV0520101-01	RV-H05	RV-201	RV-P01	RV-S01	-
1613085C91	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
1614086C1	RV0222402-03	RV-H02	RV-224	RV-P02	RV-S03	New Fan Required
1614086C2	RV0222402-03	RV-H02	RV-224	RV-P02	RV-S03	New Fan Required
1614087C1	RV0222402-03	RV-H02	RV-224	RV-P02	RV-S03	New Fan Required
1614087C2	RV0222402-03	RV-H02	RV-224	RV-P02	RV-S03	New Fan Required
1614914C1	RV0120702-00	RV-H01	RV-207	RV-P02	-	New Fan Required
1614914C2	RV0120702-00	RV-H01	RV-207	RV-P02	-	New Fan Required
1651724C1	RV0420201-00	RV-H04	RV-202	RV-P01	-	-
1652591C1	RV0420201-00	RV-H04	RV-202	RV-P01	-	-
1654584C1	RV0221500-00	RV-H02	RV-215	-	-	-
1654586C1	RV0520203-00	RV-H05	RV-202	RV-P03	-	-
1654587C1	RV0520201-00	RV-H05	RV-202	RV-P01	-	-
1654587C2	RV0520201-00	RV-H05	RV-202	RV-P01	-	-
1654589C1	RV0420201-00	RV-H04	RV-202	RV-P01	-	-
1656773C91	RV0720201-00	RV-H07	RV-202	RV-P01	-	-
1657078C91	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
1657424C91	RV0620101-00	RV-H06	RV-201	RV-P01	-	-
1657425C91	RV0620101-01	RV-H06	RV-201	RV-P01	RV-S01	-
1659713C1	RV0222402-03	RV-H02	RV-224	RV-P02	RV-S03	New Fan Required
1659949C1	RV0420201-00	RV-H04	RV-202	RV-P01	-	-
1660907C91	RV0420201-00	RV-H04	RV-202	RV-P01	-	-
1665310C1	RV0220813-00	RV-H02	RV-208	RV-P13	RV-S03	New Fan Required
1666056C91	RV0620101-01	RV-H06	RV-201	RV-P01	RV-S01	-
1666056C92	RV0620101-01	RV-H06	RV-201	RV-P01	RV-S01	-
1666955C1	RV0120702-00	RV-H01	RV-207	RV-P02	-	New Fan Required
1668811C1	RV0222200-00	RV-H02	RV-222	-	-	-
1672963C1	RV0122800-02	RV-H01	RV-228	-	RV-S02	New Fan Required
1673889C1	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
1673889C91	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
1689479C1	RV0410200-00	RV-H04	RV-102	-	-	-
1689480C1	RV0211800-00	RV-H02	RV-118	-	-	-
1689481C1	RV0410200-00	RV-H04	RV-102	-	-	-
1689481C2	RV0410200-00	RV-H04	RV-102	-	-	-
1689482C1	RV0411500-00	RV-H04	RV-115	-	-	-
1689936C1	RV0211900-00	RV-H02	RV-119	-	-	-
1690060C1	RV0211900-00	RV-H02	RV-119	-	-	-
1696302C1	RV0222200-00	RV-H02	RV-222	-	-	-
2001023C1	RV0410500-00	RV-H04	RV-105	-	-	-
2004860C1	RV0410500-00	RV-H04	RV-105	-	-	-
2005257C1	RV0610500-00	RV-H06	RV-105	-	-	-
2009769C1	RV0610500-01	RV-H06	RV-105	-	RV-S01	-
2014041C1	RV0120702-00	RV-H01	RV-207	RV-P02	-	New Fan Required
2014041C2	RV0120702-00	RV-H01	RV-207	RV-P02	-	New Fan Required
2014042C1	RV0122800-02	RV-H01	RV-228	-	RV-S02	New Fan Required
2021376C1	RV0410500-00	RV-H04	RV-105	-	-	-
2021954C1	RV0410500-00	RV-H04	RV-105	-	-	-
2022685C1	RV0111100-00	RV-H01	RV-111	-	-	-
2022686C1	RV0311100-00	RV-H03*	RV-111	-	-	-
2027495C1	RV0410500-00	RV-H04	RV-105	-	-	-

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
2029206C1	RV0410500-00	RV-H04	RV-105	-	-	-
2033827C1	RV0311100-00	RV-H03*	RV-111	-	-	-
2038840C1	RV0311100-00	RV-H03*	RV-111	-	-	-
2587815C1	RV0311100-00	RV-H03*	RV-111	-	-	-
2591440C93	RV0410100-00	RV-H04	RV-101	-	-	-
2599303C1	RV0311100-00	RV-H03*	RV-111	-	-	-
2599304C1	RV0122200-00	RV-H01	RV-222	-	-	-
2599305C1	RV0121500-00	RV-H01	RV-215	-	-	-
2599306C1	RV0120301-03	RV-H01	RV-203	RV-P01	RV-S03	-
2599307C1	RV0420201-00	RV-H04	RV-202	RV-P01	RV-S03	-
2599312C1	RV0220301-03	RV-H02	RV-203	RV-P01	RV-S03	-
2599314C1	RV0520201-00	RV-H05	RV-202	RV-P01	-	-
2600368C92	RV0620101-00	RV-H06	RV-201	RV-P01	-	-
2601077C1	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
2601973C1	RV0311100-00	RV-H03*	RV-111	-	-	-
2601974C1	RV0210900-00	RV-H02	RV-109	-	-	-
2601975C1	RV0210900-00	RV-H02	RV-109	-	-	-
2602036C1	RV0210800-03	RV-H02	RV-108	-	RV-S03	-
2602037C91	RV0410200-00	RV-H04	RV-102	-	-	-
2602038C1	RV0210900-00	RV-H02	RV-109	-	-	-
2602039C1	RV0210700-00	RV-H02	RV-107	-	-	-
2602040C1	RV0210600-00	RV-H02	RV-106	-	-	-
2602041C1	RV0311100-00	RV-H03*	RV-111	-	-	-
2602044C1	RV0311100-00	RV-H03*	RV-111	-	-	-
2602192C1	RV0211700-00	RV-H02	RV-117	-	-	-
2602193C1	RV0210900-00	RV-H02	RV-109	-	-	-
2997433C1	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
3514275C1	RV0312300-00	RV-H03*	RV-123	-	-	-
3516398C1	RV0510500-00	RV-H05	RV-105	-	-	-
3522786C2	RV0210900-00	RV-H02	RV-109	-	-	-
3522786C3	RV0210900-00	RV-H02	RV-109	-	-	-
3522788C2	RV0410500-00	RV-H04	RV-105	-	-	-
3522788C3	RV0410500-00	RV-H04	RV-105	-	-	-
3522788C91	RV0410500-00	RV-H04	RV-105	-	-	-
3533032C3	RV0210900-00	RV-H02	RV-109	-	-	-
3540116C2	RV0610500-00	RV-H06	RV-105	-	-	-
3540116C3	RV0610500-00	RV-H06	RV-105	-	-	-
3540116C4	RV0610500-00	RV-H06	RV-105	-	-	-
3540983C1	RV0311100-00	RV-H03*	RV-111	-	-	-
3540983C2	RV0311100-00	RV-H03*	RV-111	-	-	-
3540983C3	RV0311100-00	RV-H03*	RV-111	-	-	-
3540984C1	RV0311100-00	RV-H03*	RV-111	-	-	-
3540984C2	RV0311100-00	RV-H03*	RV-111	-	-	-
3540985C2	RV0210900-00	RV-H02	RV-109	-	-	-
3540985C3	RV0210900-00	RV-H02	RV-109	-	-	-
3546534C2	RV0210700-00	RV-H02	RV-107	-	-	-
3547775C2	RV0311100-00	RV-H03*	RV-111	-	-	-
3547775C3	RV0311100-00	RV-H03*	RV-111	-	-	-
3552595C1	RV0410500-00	RV-H04	RV-105	-	-	-
3552595C3	RV0410500-00	RV-H04	RV-105	-	-	-
3552595C4	RV0510500-00	RV-H05	RV-105	-	-	-
3584438C1	RV0610400-03	RV-H06	RV-104	-	RV-S03	-
3584438C1	RV0610400-03	RV-H06	RV-104	-	RV-S03	-
3584438C2	RV0610400-03	RV-H06	RV-104	-	RV-S03	-
3584438C3	RV0610400-03	RV-H06	RV-104	-	RV-S03	-

* Thread bracket clockwise into RV-H03

INTERNATIONAL

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
3584452C1	RV0210800-03	RV-H02	RV-108	-	RV-S03	-
3585866C1	RV0211700-00	RV-H02	RV-117	-	-	-
3586345C2	RV0210600-00	RV-H02	RV-106	-	-	-
3588739C1	RV0410100-00	RV-H04	RV-101	-	-	-
3588739C1	RV0410100-00	RV-H04	RV-101	-	-	-
3588739C2	RV0410100-00	RV-H04	RV-101	-	-	-
3609117C2	RV0710400-03	RV-H07	RV-104	-	RV-S03	-
3611897C2	RV0710500-00	RV-H07	RV-105	-	-	-
3615038C3	RV0410300-00	RV-H04	RV-103	-	-	-
3615038C4	RV0410300-00	RV-H04	RV-103	-	-	-
3812002C1	RV0410100-00	RV-H04	RV-101	-	-	-
507271C2	RV0520101-01	RV-H05	RV-201	RV-P01	RV-S01	-
537481C2	RV0220301-00	RV-H02	RV-203	RV-P01	-	-
YB-3000	RV0210600-00	RV-H02	RV-106	-	-	-
YB-3130	RV0210800-03	RV-H02	RV-108	-	RV-S03	-
YB-625	RV0410500-00	RV-H04	RV-105	-	-	-
YB-626	RV0210700-00	RV-H02	RV-107	-	-	-

MACK

2MH354AP2	RV0220300-00	RV-H02	RV-203	-	-	-
38MH31	RV0220300-00	RV-H02	RV-203	-	-	-
38MH31AP1	RV0220300-00	RV-H02	RV-203	-	-	-
38MH31AP2	RV0220300-00	RV-H02	RV-203	-	-	-
38MH31P2	RV0220300-00	RV-H02	RV-203	-	-	-
38MH37	RV0220300-00	RV-H02	RV-203	-	-	-
38MH37A	RV0220300-00	RV-H02	RV-203	-	-	-
38MH37AP2	RV0220300-00	RV-H02	RV-203	-	-	-
38MH37AP2	RV0220300-00	RV-H02	RV-203	-	-	-
38MH416	RV0220300-00	RV-H02	RV-203	-	-	-
38MH416P1	RV0220300-00	RV-H02	RV-203	-	-	-
38MH416P2	RV0220300-00	RV-H02	RV-203	-	-	-
38MH420	RV0222300-00	RV-H02	RV-223	-	-	-
38MH318	RV0420100-00	RV-H04	RV-201	-	-	-
38MH414M	RV0420100-00	RV-H04	RV-201	-	-	-
38MH424M	RV0420100-00	RV-H04	RV-201	-	-	-
38MH423M	RV0420200-00	RV-H04	RV-202	-	-	-
38MH304	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
38MH313	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
1MH29305BP2	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
1MH29305BP3	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
1MH29305P2	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
1MH29305P2	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
38MH317A	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
38MH315A	RV0721304-01	RV-H07	RV-213	RV-P04	RV-S01	-

PETERBILT

05-18431-000	RV0422005-00	RV-H04	RV-220	RV-P05	-	-
05-18815-000	RV0521000-00	RV-H05	RV-210	-	-	-
05-18815-000	RV0521000-00	RV-H05	RV-210	-	-	-
05-18953-000	RV0522005-00	RV-H05	RV-220	RV-P05	-	-
05-19326-000	RV0720201-00	RV-H07	RV-202	RV-P01	-	-
05-19373-000	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
05-19383-000	RV0820700-00	RV-H08	RV-207	-	-	-
05-19481-000	RV0420101-00	RV-H04	RV-201	RV-P01	-	-

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
166054	RV0410500-00	RV-H04	RV-105	-	-	-
166223	RV0610500-00	RV-H06	RV-105	-	-	-
166283	RV0410500-00	RV-H04	RV-105	-	-	-
166301	RV0120702-00	RV-H01	RV-207	RV-P02	-	New Fan Required
166302	RV0222402-03	RV-H02	RV-224	RV-P02	RV-S03	New Fan Required
166303	RV0222402-03	RV-H02	RV-224	RV-P02	RV-S03	New Fan Required
166305	RV0122800-02	RV-H01	RV-228	-	RV-S02	New Fan Required
166306	RV0120702-00	RV-H01	RV-207	RV-P02	-	New Fan Required
166314	RV0310600-02	RV-H03*	RV-106	-	RV-S02	-
166400	RV0210600-02	RV-H02	RV-106	-	RV-S02	New Fan Required
166499	RV0610500-01	RV-H06	RV-105	-	RV-S01	-
166881	RV0111100-00	RV-H01	RV-111	-	-	-
167046	RV0410500-00	RV-H04	RV-105	-	-	-
167047	RV0410500-00	RV-H04	RV-105	-	-	-
167071	RV0311100-00	RV-H03*	RV-111	-	-	-
167118	RV0410200-00	RV-H04	RV-102	-	-	-
167119	RV0120702-00	RV-H01	RV-207	RV-P02	-	New Fan Required
167121	RV0222700-00	RV-H02	RV-227	-	-	-
167222	RV0222200-00	RV-H02	RV-222	-	-	-
167341	RV0410500-00	RV-H04	RV-105	-	-	-
167421	RV0311100-00	RV-H03*	RV-111	-	-	-
167524	RV0410500-00	RV-H04	RV-105	-	-	-
167852	RV0312300-00	RV-H03*	RV-123	-	-	-
167981	RV0311100-00	RV-H03*	RV-111	-	-	-
168395	RV0311000-02	RV-H03*	RV-110	-	RV-S02	-
168559	RV0310600-02	RV-H03*	RV-106	-	RV-S02	-
168815	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
168821	RV0420100-00	RV-H04	RV-201	-	-	-
169238	RV0112000-02	RV-H01	RV-120	-	RV-S02	-
169308	RV0122400-03	RV-H01	RV-224	-	RV-S03	New Fan Required
169366	RV0410200-00	RV-H04	RV-102	-	-	-
169380	RV0312300-00	RV-H03*	RV-123	-	-	-
169422	RV0510500-00	RV-H05	RV-105	-	-	-
169575	RV0410500-00	RV-H04	RV-105	-	-	-
169683	RV0410500-00	RV-H04	RV-105	-	-	-
169684	RV0410500-00	RV-H04	RV-105	-	-	-
170337	RV0220702-00	RV-H02	RV-207	RV-P02	-	New Fan Required
183125	RV0220300-00	RV-H02	RV-203	-	-	-
183831	RV0221600-00	RV-H02	RV-216	-	-	-
184394	RV0221700-00	RV-H02	RV-217	-	-	-
186315	RV0720100-01	RV-H07	RV-201	-	RV-S01	-
186345	RV0220301-00	RV-H02	RV-203	RV-P01	-	-
187170	RV0221714-00	RV-H02	RV-217	RV-P14	-	-
187182	RV0520101-01	RV-H05	RV-201	RV-P01	RV-S01	-
187242	RV0220301-00	RV-H02	RV-203	RV-P01	-	-
187415	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
187604	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
187605	RV0720111-01	RV-H07	RV-201	RV-P11	RV-S01	-
187745	RV0720111-00	RV-H07	RV-201	RV-P11	-	-
188206	RV0720201-00	RV-H07	RV-202	RV-P01	-	-
188209	RV0520101-01	RV-H05	RV-201	RV-P01	RV-S01	-
188607	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
188640	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
188667	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
188723	RV0421315-01	RV-H04	RV-213	RV-P15	RV-S01	-

* Thread bracket clockwise into RV-H03

SCHWITZER

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
189176	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
189812	RV0221500-00	RV-H02	RV-215	-	-	-
191431	RV0220300-00	RV-H02	RV-203	-	-	-
192006	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
192034	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
192037	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
192051	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
192155	RV0210600-02	RV-H02	RV-106	-	RV-S02	-
192312	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
192361	RV0110600-02	RV-H01	RV-106	-	RV-S02	New Fan Required
192372	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
192379	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
192497	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
194020	RV0720900-01	RV-H07	RV-209	-	RV-S01	-
194021	RV0721000-01	RV-H07	RV-210	-	RV-S01	-
194038	RV0221500-00	RV-H02	RV-215	-	-	-
194169	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
194182	RV0520100-01	RV-H05	RV-201	-	RV-S01	-
194189	RV0720111-01	RV-H07	RV-201	RV-P11	RV-S01	-
194374	RV0720201-00	RV-H07	RV-202	RV-P01	-	-
194767	RV0520101-01	RV-H05	RV-201	RV-P01	RV-S01	-
194862	RV0220300-00	RV-H02	RV-203	-	-	-
194974	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
194986	RV0420201-00	RV-H04	RV-202	RV-P01	-	-
196002	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
196054	RV0222300-00	RV-H02	RV-223	-	-	-
196102	RV0520203-00	RV-H05	RV-202	RV-P03	-	-
196103	RV0520201-00	RV-H05	RV-202	RV-P01	-	-
196131	RV0122300-00	RV-H01	RV-223	-	-	-
196133	RV0620101-01	RV-H06	RV-201	RV-P01	RV-S01	-
196135	RV0620101-00	RV-H06	RV-201	RV-P01	-	-
196181	RV0420201-00	RV-H04	RV-202	RV-P01	-	-
196291	RV0420201-00	RV-H04	RV-202	RV-P01	-	-
196408	RV0720900-01	RV-H07	RV-209	-	RV-S01	-
196567	RV0221714-00	RV-H02	RV-217	RV-P14	-	-
196568	RV0212200-00	RV-H02	RV-122	-	-	-
196704	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
196753	RV0420100-00	RV-H04	RV-201	-	-	-
196932	RV0720201-01	RV-H07	RV-202	RV-P01	-	-
197189	RV0521200-00	RV-H05	RV-212	-	-	-
197703	RV0721304-01	RV-H07	RV-213	RV-P04	RV-S01	-
197778	RV0620101-01	RV-H06	RV-201	RV-P01	RV-S01	-
197780	RV0411200-00	RV-H04	RV-112	-	-	-
197805	RV0620101-01	RV-H06	RV-201	RV-P01	RV-S01	-
197853	RV0420101-00	RV-H04	RV-201	RV-P01	-	-
197874	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
197879	RV0420201-00	RV-H04	RV-202	RV-P01	-	-
198038	RV0521200-00	RV-H05	RV-212	-	-	-
198039	RV0412100-00	RV-H04	RV-121	-	-	-
198057	RV0220300-00	RV-H02	RV-203	-	-	-
198195	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
198197	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
198212	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
198241	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
198242	RV0720101-00	RV-H07	RV-201	RV-P01	-	-

OEM#	Kit Masters #	Head	Bracket	Pilot Adapter	Special	Notes
198387	RV0520116-01	RV-H05	RV-201	RV-P16	RV-S01	-
198859	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
199076	RV0520900-01	RV-H05	RV-209	-	RV-S01	-
199159	RV0221714-00	RV-H02	RV-217	RV-P14	-	-
199463	RV0222700-00	RV-H02	RV-227	-	-	-
199511	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
199628	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
199807	RV0410200-00	RV-H04	RV-102	-	-	-
199809	RV0211900-00	RV-H02	RV-119	-	-	-
199810	RV0410200-00	RV-H04	RV-102	-	-	-
199811	RV0211800-00	RV-H02	RV-118	-	-	-
199812	RV0411500-00	RV-H04	RV-115	-	-	-
199840	RV0721400-00	RV-H07	RV-214	-	-	-

VOLVO

1118850	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
1119912	RV0220300-00	RV-H02	RV-203	-	-	-
1119915	RV0520101-01	RV-H05	RV-201	RV-P01	RV-S01	-
1119916	RV0220300-00	RV-H02	RV-203	-	-	-
1675036	RV0722100-00	RV-H07	RV-221	-	-	-
2045349	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
2092619	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
3918904	RV0221500-00	RV-H02	RV-215	-	-	-
3945142	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
3945142	RV0520101-00	RV-H05	RV-201	RV-P01	-	-
15044771	RV0411400-00	RV-H04	RV-114	-	-	-
15504174	RV0220303-00	RV-H02	RV-203	RV-P03	-	-
15684550	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
15716073	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
15718025	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
15767378	RV0110600-00	RV-H01	RV-106	-	-	-
15990495	RV0110600-02	RV-H01	RV-106	-	RV-S02	-
15990496	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
15995659	RV0411200-02	RV-H04	RV-112	-	RV-S02	-
22578203	RV0122300-00	RV-H01	RV-223	-	-	-
20811-3207	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
20822-0019	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
20822-0022	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
20822-0035	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
20822-0126	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
20822-0130	RV0720201-00	RV-H07	RV-202	RV-P01	-	-
20822-0170	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
20822-0188	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
20822-3206	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
20822-3207	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-
20822-3208	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
20822-3209	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
20822-3459	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
20822-3463	RV0720101-00	RV-H07	RV-201	RV-P01	-	-
20822-3617	RV0720101-01	RV-H07	RV-201	RV-P01	RV-S01	-



SPECTRUM[®]

MODULAR VISCOUS FAN DRIVES
by Kit Masters

KIT MASTERS

825 1st Street N.E. • Perham, Minnesota 56573

Toll-Free: 800-810-9110

Telephone: 218-346-2121

Fax: 218-347-5487

Email: sales@kit-masters.com

www.kit-masters.com